


Project Location



Post-repair runoff rate & volume off-site


| 24-Hour Rainfall | Runoff Rate [cfs] | Runoff Volume [cf] |
|-----------------------------|------------------------------|-------------------------------|
| 2-year [2.8"] | 0.0 | 0.0 |
| 5-year [3.6"] | 0.4 | 9278.3 |
| 10-year [4.2"] | 1.0 | 18556.6 |
| 100-year [5.9"] | 5.2 | 50703.8 |

Fen Breach 1




Fen Breach 1 & 2

- Flow
- Const Area



Fen Breach Repair




Fen Breach Repair

FILL STREET CAR
BED BREACH 1 & 2 TO
MATCH GRADE AT
ELEVATION 985

CL. BREACH 1
STA. 18+39.85

CL. BREACH 2
STA. 18+65.83

PROFILE A



STREET CAR SIDE
SLOPE TO CONFORM
TO ADJACENT SLOPE

PROFILE B

