



Figure 1. Floodplain dominated by buckthorn and young boxelder



Figure 2. Floodplain dominated by buckthorn and young boxelder



Figure 3. Only boxelder proposed for removal on this bank



Figure 4. Floodplain near Neal Avenue. Large trees to be preserved for snag habitat



Figure 5. Collapsed stream banks and poor riparian vegetation dominated by common buckthorn and boxelder



Figure 6. Image showing extent of common buckthorn within the floodplain



Figure 7. Large diameter silver maple and black willow to be preserved for snag habitat



Figure 8. Example of young boxelder



Figure 9. Fall image showing young boxelder



Figure 10. Typical understory in floodplain dominated by common buckthorn



Figure 11. Typical understory in floodplain dominated by common buckthorn



Figure 12. Typical understory in floodplain dominated by common buckthorn